




FLYNN ENVIRONMENTAL, INC.

UST Corrective Actions Ashtabula County, OH

- ✓ Tier 2 Evaluation
- ✓ Soil Excavation
- ✓ Fate & Transport Modeling
- ✓ NFA

A gasoline release occurred in August 1998 when a product line was broken during a cathodic protection system upgrade. Another consulting company conducted a site assessment and monitored groundwater for eight years, but little else was accomplished to correct the problem. Flynn was hired in November 2006 to complete the project. Flynn immediately obtained the necessary off-site access to complete the site assessment and excavated the majority of the soil contamination in May 2007. Flynn used fate and transport modeling confirmed by quarterly groundwater monitoring in order to show that the residual contamination would

not pose a risk to human health or the environment. The site received a No Further Action letter from BUSTR one year after the soil excavation.



GROUNDWATER CONCENTRATIONS

Maximum Concentrations	Benzene (µg/l)	Toluene (µg/l)	Ethylbenzene (µg/l)	Xylenes (µg/l)	MTBE (µg/l)
Pre-Excavation	5,069	4,834	2,237	13,500	500
Post-Excavation	202	14	10	15	38

FLYNN ENVIRONMENTAL, INC.

5640 Whipple Avenue NW
Suite 1
North Canton, OH 44720
ph: 330-499-1000
fax: 330-499-4499

1-800-690-9409

www.flynnenvironmental.com